


Moderate load maximum latency
ARM Broadcom BCM2708 00 MHz, Linux 4.1.15-rt15 vs.
ARM Broadcom BCM2835 400 MHz, Linux 4.18.16-rt9



(Plotted on 05/17/25 at 12:20:42)

Core 0 —+—