


Moderate load maximum latency  
ARM Broadcom BCM2708 00 MHz, Linux 4.1.15-rt15 vs.  
ARM Broadcom BCM2835 400 MHz, Linux 4.18.16-rt9



(Plotted on 11/12/24 at 8:57:17)

Core 0 —+—